

REGULATORY BRANCH FAX Cover Sheet

DATE: October 20, 2004

FAX Number: 215-814-2302

TO: Mr. Chuck Schadel

Location: EPA

Telephone Number: 215-814-5761

FROM: Michael F. Green

Location: U.S. Army Corps of Engineers

Telephone Number: 215-656-6836

Remarks: WOODS AT NORTHAMPTON info.

Number of Pages: ______ (including cover sheet)

Our FAX Number is (215) 656-6724.

ATTENTION!

DO NOT PROCESS, STORE, OR TRANSMIT CLASSIFIED INFORMATION ON UNSECURED TELECOMMUNICATIONS SYSTEMS. OFFICIAL DOD TELECOMMUNICATIONS SYSTEMS, INCLUDING FACSIMILE MACHINES, ARE SUBJECT TO MONITORING FOR TELECOMMUNICATIONS SECURITY MONITORING AT ALL TIMES. USE OF THIS SYSTEM CONSTITUTES CONSENT TO TELECOMMUNICATIONS SECURITY MONITORING.

CERTIFIED MAIL - RETURN RECEIPT REQUESTED



DEPARTMENT OF THE ARMY

PHILADELPHIA DISTRICT, CORPS OF ENGINEERS WANAMAKER BUILDING, 100 PENN SQUARE LAST PHILADELPHIA, PENNSYLVANIA 19107-3390

Regulatory Branch Surveillance and Enforcement Section

JUL 2 7 2004

SUBJECT:

CENAP-OP-R-200400415 Violation

CENAP-OP-R-200100167-PASPGP-2

PADEP #: E09-828

CENAP-OP-R-200000350-JD

Mr. Dennis P. LaRosa K. Hovnanian Companies, Inc. Makefield Executive Quarters 301 Oxford Valley Road Suite 84 Yardley, Pennsylvania 19067

Dear Mr. LaRosa:

This letter is written with regard to our letter to Mr. Scott E. Bush, Exponent, Exton, Pennsylvania, dated October 29, 2002, authorizing K. Hovnanian Companies, Inc., Yardley, Pennsylvania, to perform regulated work under the authority of Pennsylvania State Programmatic General Permit #2 (CENAP-OP-R-200100167-PASPGP-2), to construct "The Woods at Northampton" residential development, Northampton Township, Bucks County, Pennsylvania. The Pennsylvania Department of Environmental Protection (PADEP) authorization number is #E09-828.

The authorized work includes the discharge of dredged and/or fill material to construct three box culverts, four road crossings, three utility line crossings (water and sewer), one outfall structure, and to perform temporary dewatering activities in waters of the United States, including wetlands, on property located along Jackson Road (Pennsylvania State Route 322), in Northampton Township, Bucks County, Pennsylvania. The approved work is shown on eight project plans entitled, "Grading Plan View A", "Grading Plan View C", "Grading Plan View D", "Grading Plan View E", "Grading Plan View F" and "Grading Plan View G", dated March 13, 2000, last revised December 2, 2001, and, "Grading Plan View B" and "Grading Plan View II", dated March 13, 2000, last revised April 10, 2002, sheets 16 through 23, prepared by Showalter and Associates, Chalford, Pennsylvania, scale 1 inch equals 50 feet.

A copy of the above-noted Federal authorization (CENAP-OP-R-200100167-PASPGP-2) was furnished to Mr. Dennis P. LaRosa, K. Hovnanian Companies, Inc., Yardley, Pennsylvania on October 29, 2002.

On May 27, 2004, this office was notified by the Bucks County Conservation District (BCCD) that appropriate soil erosion and sedimentation controls had not been installed on the site in accordance with State laws and the Best Management Practice requirements of the PASPGP-2 authorization. The BCCD indicated that they had issued five Earth Disturbance Inspection Reports to K. Hovnanian Companies, Inc., identifying numerous violations for the period November 3, 2003 through May 27, 2004. Furthermore, the BCCD notified this office that K. Hovnanian Companies, Inc. may have performed unauthorized regulated work not approved by the above-noted permit.

Inspection by personnel of this office on June 2, 2004 and June 22, 2004, revealed that in addition to your failure to install the required soil crosion and sedimentation controls, regulated work, including the discharge of dredged and/or fill material into waters of the United States, including wetlands, had been performed on the site in non-compliance with the following Special Conditions of the above-noted PASPGP-2:

a. Special Condition "1" states, "All work performed in association with the above noted project shall be conducted in accordance with the project plans identified as 'Grading Plan...', prepared by Showalter & Associates, dated March 13, 2000, last revised December 2, 2001, and April 10, 2002, sheets 16 through 23 of 72."

During his site inspection on June 2, 2004, Mr. Michael Green of this office identified that while Crossing #5 was authorized as a utility line crossing (Grading Plan View F, Sheet 21 if 72), it had been temporarily filled and was being utilized as a road crossing for the transport of vehicles and/or equipment to develop part of "The Woods at Northampton" residential development.

b. Special Condition "3" states, "Any deviation in construction methodology or project design from that shown on the above noted drawings must be approved by this office, in writing, prior to performance of the work. All modifications to the above noted project plans shall be approved, in writing, by this office. No work shall be performed prior to written approval of this office."

This office did not receive any request by K. Hovnanian Companies, Inc. to modify the approved project plans to allow the use of Crossing #5 as a road crossing. This office did not issue written approval to K. Hovnanian Companies Inc. to utilize Crossing #5 as a road crossing.

c. Special Condition "15" states, "That upon completion of the utility (water and sewer mains) installations within waters and wetlands of the U.S., all wetlands and waters of the U.S. disturbed during construction shall be returned to their conditions prior to project implementation. These areas shall be replanted with indigenous species presently inhabiting the forested wetland areas."

A site inspection on June 22, 2004 by Mr. Green revealed that the unauthorized temporary road crossing, Crossing #5, had been removed and the area had been re-graded and stabilized. The area however, had not been replanted with indigenous species presently inhabiting the forested wetlands areas. Furthermore, this office has not yet verified that the site has been returned to the grade that existed prior to project implementation. Additional investigation of this area is being coordinated with Mr. Scott Bush. In the event that the area of disturbance at Crossing #5 has not been returned to the grade that existed prior to the performance of work additional regrading and/or planting of this area may be required.

The work performed in noncompliance with the above noted permit is a violation Section 404 of the Clean Water Act.

Since you have not been granted a permit for the above noted unauthorized work, you are directed to cease and desist from conducting or permitting any further work of this nature in areas subject to Federal jurisdiction.

In order to facilitate resolution of your violation, you are requested to contact Mr. Michael Green of this office, within five days of the date of this letter, to arrange a meeting. The purpose of the meeting is to discuss the above-noted violations, possible enforcement actions and ways to resolve the violations. You may reach Mr. Green by calling (215) 656-6836.

Please be advised that the performance of work in non-compliance with the abovenoted permit, including Special Conditions, may subject you to administrative, civil, and/or criminal enforcement action, including administrative, civil, and/or criminal fines.

This letter does not affect your responsibility to obtain any other Federal, State, or local approvals required by law for the above noted work.

Should you have any questions concerning this matter, please contact Mr. Green of this office at (215) 656-6836.

Sincerely,

Frank LaCianfran

Chief, Regulatory Branch

Copies Furnished:

US Fish and Wildlife Service, Eastern PA Field Office US Environmental Protection Agency, Region III, PA PA Department of Environmental Protection, Norristown, PA Northampton Township Bucks County Soil Conservation District



September 30, 2004

MICHAEL Mr. Jeffrey Green Department of the Army Philadelphia District, Corps of Engineers Wanamaker Building, 100 Penn Square East Philadelphia, PA 19107-3390

K. Hovannian to Heritage Conservancy contribution Rc:

Dear Mr. Green:

Hentage Conservancy is in receipt of a contribution from K. Hovnanian at Northampton, L.L.C. in the amount of \$27,500. This contribution was negotiated as part of the resolution of an issue of non-compliance with conditions set forth in the permits that Hovnanian received from the Pennsylvania Department of Environmental Protection.

It is the conservancy's understanding that the funds must to be used to purchase waters, wetlands, and associated upland buffers and/or purchase conservation casements over waters, wetlands, and associated upland buffers in Bucks County, Pennsylvania.

Please do not hesitate to call me at 215-345-7020, ext. 113, if you require further information.

Sincerely.

Grey L Marshall my

Vice President of Resource Protection

JLM:smy

ct: Rick Buchholz, K. Hovnanian

- Honorable William Hart Rufe III vice that more Mitwin L. Woodsill: THURSDAY Michael Maliney --Secretary . . Robert L. Russell

ductions .. Carl M. Asplundh Jr. Christopher 8 Chandor Edg. John W. Clemen Coording & Color Groge Donovan ALLA William H. Eastburn Inc Eng. DE VALLE CHECKE FACHE Bizahetalt Gemmin Beg. ... J. Lawrence Grin Ji. 154. Lewis W. Hilli Charles D'Lomits Johnes W. Marb. Pag. Jonathan E. Dito ... Ferrity Reynolds Contobust Story ... Christine C. Sodennan.

President CHITTOM C DAVID IT


John H. Threnpron

Directors Enerios Robert L. Byers William, F. Meether, Eco. . . F Joseph R. Kempter C.P.A. Mangaret & Peny

in diamondia like DOYLEROWN, PA. 1 15901-2489.

OS1,345-1820 1215) 345 4328 Max

www.helicajeconservancyor



Mr. Eric Wightman
Environmental Protection Specialist
Bucks County Conservation District
1456 Ferry Road, Suite 704
Doylestown, PA 18901

RE: Earth Disturbance Inspection Report #14 – April 25, 2005

Woods at Northampton

PAR1OD526

Northampton Township

Dear Eric.

On April 29, 2005 K. Hovnanian at Northampton, LLC received the above referenced report for the Woods at Northampton Community. I would like to address two issues noted in the Site Description and Observations section.

First, your inspection report notes that you observed a failure to stabilize and install proper lining in swale # 7. Swale #7 conveys significant amounts of drainage that originates from an adjacent off-site farm. This condition had been identified during our own inspection of the site, which occurred on April 18. We installed stone filters in the swale on that date as a temporary measure until the previously installed storm-damaged lining could be replaced. The work was identified, temporarily remediated, and scheduled for permanent replacement prior to receipt of the inspection report which we received on April 29, 2005. I have enclosed photos of the swale which were taken on May 4, 2005 showing the completed swale.

The second issue set forth in the inspection report states a "failure to provide inspection logs." The note could be misinterpreted to mean that you asked for the logs but we were unable to provide them, which is not the case. We did not know of your visit on April 25, 2005, nor were any of our field personnel asked to provide you with a copy of the applicable inspection logs. We have been keeping accurate inspection logs for this site in conformance with the permit. I am attaching a copy of the most recent inspection reports herewith, which indicate that the self- inspection and order for corrective work was underway prior receipt of the April 25, Inspection Report.

At our meeting on March 10, 2005, I believe that you stated that, due to the number of sites you need to visit, you did not have the time to track down our people in the field when you visited our site. This may be the reason why you were not able to contact the appropriate field personnel to review the inspection log during the April 25 inspection. Please note, however, that all of our site-based Superintendents have Nextel cell phones, which numbers I believe you have or I can provide you with. Alternatively, if you do not wish to notify us when you arrive at our site for an inspection, I would like to arrange a place where the logs are kept for your inspection when visiting our community. I believe, however, that the best way to assure that your inspections are complete and accurate is to have our Superintendents accompany you during the inspections. This procedure would be in addition to the normal maintenance and inspections that we are conducting.

I look forward to your next inspection, and would appreciate you letting us know of any suggestions that you have to ensure that the inspection logs are available for your review, so we can avoid any future implication that we did not have them, or that we failed to provide them. If I can assist in this matter in any way please feel free to contact me at 215-357-7723.

Sincerely,

K. Hovanian at Northampton, LLC

Rick Buchholz

Sr. Community Manager

cc:

Enclosure

Frederick Groshens, District Manager (w/o enclosure)

Larry Lutz

Mike Stadulis

Elizabeth Hurtubise, Esq.

3630-FM-WQ0090 Rev. 4/2000

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

Report	No.
--------	-----

1

344	
	. ,≎

EARTH DISTURBANCE INSPECTION REPORT

_	_		LANTII DISTUNDAN		INOI LOTION	ILLI O	1 . 1	4410100
Tax	Parce	el#	31-5-19			lr	nspec	tion Date
Cert	ified I	Mail # 81	64/8157			bucks		
Proj	ect n	name WO	DDS			Tot	tal Pro	oject area 139.00
Loc	ation	JACKSON	NVILLE RD					
Mun	icipa	ality NOR	THAMPTON TWP					-
Rec	eivin	g water(s)	TRIB TO LITTLE NESHAMINY C	REE	Chapter 9	3 designa	ation	WWF MF
	-	sible party	K. HOVANANIAN@NORTHAMP	TON	LLC CVA IN	VC		
(name	& address)	385 OXFORD VALLEY RD		110 CE	ENTRAL A	AVE	
			YARDLEY PA 19067		FAIRL	ESS HILL	SPA	19030
		Phone	()		()		
Wea	ather	conditions				Time of	f Insp	ection 10:00:00 AM
			(name & title) UNKNOWN		Inspec	•	-	HTMAN
Тур	e of	Inspection (check only one)	Ph	notographs taken	Yes ⊠		No 🗌
Rou	tine (complete 🛚	Routine partial	Follow	v-up □	Comple	aint 🗌	Final 🗌
Site	Des	scription & (Observations 1. FAILURE TO S	TABI	LIZE ALL DISTUR	BED GR	OUND	ACCORDING TO PLAN
72 l	HOU	R NOTICE.	2. FAILURE TO MAINTAINAN INS	TALL	SILT FENCE ACC	ORDING	TOF	LAN ENTIRE PROJECT.
3. F	AILU	JRE TO STA	BILIZE AND MAINTAIN SILT FEN	CE A	CCORDING TO P	LAN AT	STRE	AM CROSSING BEHIND
LO	14+	+21. 4. FAIL	URE SEDIMENT POLLUTION O	CCU	RING AT STREAM	CROSS	ING	5 FAILURE SEDIMENT
TR/	\P #1	1 SHOULD B	E COMPLETED MAINTAINED A	ND S	TABILIZE ACCOR	DING TO	PLAN	I. 6. FAILURE TO HAVE
INS	PEC	TION LOGS.						
								continued 🗌
								continued [_]
		Darmit an	d Plan Requirements	Tyn	e of Activity (chec	rk as mar	N 25 2	innronriate)
Υ	N	r viinit all	u i ian Negunements	. yp	C OI ACTIVITY (OHE)	A UJ IIIdi	. , as a	ippi opriuto)
ı ⊠		Written Frosion	& Sediment Control Plan required		Pub. Road Constr./Mai	nt. (PRC)		Pvt. Road/Residence (PRRS)
	⊠		ment Control Plan requested	Ø	Res. Subdivision (RSB	, ,		Comm./Indust. Dev. (CMIN)
	Ø	E & S Control F	•		Govmt. Facilities (GOV)		Recreation Facilities (RECF)
Ø		NPDES Permit	Permit required	1				
		☑ Phased	•		Utilities Facilities (UTL)			Agricul. Activities (AGA)
		I lasec	•		Utilities Facilities (UTL) Sewer/Water Systems			Agricul. Activities (AGA) Oil/Gas Development (OGD)
	•	Permit #	required	l	•	(SWS)		` '

3630-FM-WQ0090a Rev. 4/2000



Report No.

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

EARTH DISTURBANCE INSPECTION REPORT

	EARTH BIOTORBANGE INOT ECTION REFORM	
Insp	ection Findings (check as many as appropriate)	Reference
a.	No violations observed at this time:	☐ (N/A)
b.	Failure to develop a written Erosion and Sediment Control Plan:	☐ (102.4)
C.	Failure to have an Erosion and Sediment Control Plan available on site:	(102. 4)
d.	Failure to submit Erosion and Sediment Control Plan as requested:	(102.4)
e.	Failure to implement effective Best Management Practices:	(102.4)
f.	Failure to maintain effective Best Management Practices:	(102.4)
g.	Failure to use Special Protection Best Management Practices for discharges to High Quality or Exceptional Value Waters:	☐ (102. 4)
h.	Failure to obtain an NPDES Permit for Stormwater Discharges Associated With a Construction Activity:	☐ (102.5)
i.	Failure to obtain an Erosion and Sediment Control Permit:	☐ (102.5)
j.	Failure to demonstrate that alternative Best Management Practices achieve regulatory standards:	☐ (102.11)
k.	Failure to permanently stabilize the earth disturbance site:	II (102.22)
1.	Failure of earth disturbance activities to comply with permit conditions:	(402 CSL)
m.	Failure to prevent sediment or other pollutant discharge into waters of the Commonwealth:	(401 CSL)
n.	Site conditions present a potential for pollution to waters of the Commonwealth:	(402 CSL)
0.	Other (describe):	
	Inspection of this project has revealed site conditions which constitute violations 92 and/or 102 and the Clean Streams Law, the act of June 22, 1937, P.L. 1987, 35 P.	
	Additional information regarding these violations can be found on the back of	of this report.
Con	pliance Assistance Measures <u>FOΦLOW EROSION CONTROL PLAN.</u>	
		continued [
roil	ow-up Inspection will occur on or about (date) 11-12-03	
	Pertifico Mil 11-5-03 Eric Wightner	11-5-03
(Sig	nature of Site Representative) (Date) (Inspector's Signature)	(Date)

The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.

3630-FM-WQ0090 Rev. 4/2000

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

Report	No.	2
--------	-----	---

|--|--|--|

FARTH DISTURBANCE INSPECTION REPORT

	EARTH DISTURDANT	CEI	NOPECTION	KEPU	Κı	
Tax Parcel #	31-5-19				spect	ion Date
Certified Mail #	8785/8778		_	bucks		
Project name _W	OODS			Tot	al Pro	ject area <u>139.00</u>
Location JACKS	ONVILLE RD					
Municipality NO	RTHAMPTON TWP					
Receiving water(s)	TRIB TO LITTLE NESHAMINY O	REEK	Chapter 93	designa	tion	WWF MF
Responsible party	K. HOVANANIAN@NORTHAMP	TON I	LLC CVA IN	IC		
(name & address)	385 OXFORD VALLEY RD		110 CE	NTRAL A	VE	
	YARDLEY PA 19067		FAIRLE	SS HILL	SPA	19030
Phon	e ())		
Weather condition	s SUNNY			Time of	Inspe	ection 1:30:00 PM
Site Representativ	e (name & title) UNKNOWN		Inspec	tor ERI	C WIGH	ITMAN
					· · · · ·	🖂
Type of Inspection			otographs taken			No 🖾
Routine complete [· -		/-up ⊠	Compla		
-	Observations UNABLE TO INSPE					
	ALL DISTURBED GROUND ACCORDING TO PLAN 72 HOUR NOTICE. 2. FAILURE TO MAINTAINAN INSTALL SILT					
	NG TO PLAN ENTIRE PROJECT					
	PLAN AT STREAM CROSSING					
	FREAM CROSSING. 5. FAILURE S				E CO	MPLETED MAINTAINED
AND STABILIZE ACCORDING TO PLAN. 6. FAILURE TO HAVE INSPECTION LOGS.						
						1.4
						continued 🗌
	and Plan Requirements	Туре	e of Activity (chec	k as man	y as a	ppropriate)
Y N			D.1. D. 10 1-21-11	(DDO)	П	P.4 Dead/Deaidenes (PDDS)
	ion & Sediment Control Plan required ediment Control Plan requested		Pub. Road Constr./Maint Res. Subdivision (RSBD	` ,		Pvt. Road/Residence (PRRS) Comm./Indust. Dev. (CMIN)
	of Permit required		Govmt. Facilities (GOV)			Recreation Facilities (RECF)
☐ ☐ NPDES Per	•		Utilities Facilities (UTL)			Agricul. Activities (AGA)
	sed Constr. Non-Phased Constr.		Sewer/Water Systems (SWS)		Oil/Gas Development (OGD)
Permit #	PAR10D526		Remediation/Restoration			Silviculture (SILV)
1						

CC/RESPONSIBLE OFFICIAL/MUNICIPAL OFFICE/MUNICIPAL ENGINEER/EW/DISTIRCT MANAGER/BCCD FILE/BCCC 31/JG

3630-FM-WQ0090a Rev. 4/2000

Report No.



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

EARTH DISTURBANCE INSPECTION REPORT

•	of a Paradiana (alamba a managara)	Reference	
Inspection Findings (check as many as appropriate)		☐ (N/A)	
۳.	No violations observed at this time:	_	
b.	Failure to develop a written Erosion and Sediment Control Plan:	[] (102.4) _	
C.	Failure to have an Erosion and Sediment Control Plan available on site:	☐ (102.4)	
d.	Failure to submit Erosion and Sediment Control Plan as requested:	(102.4)	
e.	Failure to implement effective Best Management Practices:	⊠ (102.4)	
f.	Failure to maintain effective Best Management Practices:	⊠ (102.4)	
g.	Failure to use Special Protection Best Management Practices for discharges to High Quality or Exceptional Value Waters:	☐ (102. 4)	
h.	Failure to obtain an NPDES Permit for Stormwater Discharges Associated With a Construction Activity:	☐ (102.5)	
i.	Failure to obtain an Erosion and Sediment Control Permit:	(102.5)	
j.	Failure to demonstrate that alternative Best Management Practices achieve regulatory standards:	[] (102.11)	(
k.	Failure to permanently stabilize the earth disturbance site:	⊠ (102.22)	Ć.
1.	Failure of earth disturbance activities to comply with permit conditions:		
m. Ĭ	Failure to prevent sediment or other pollutant discharge into waters of the Commonwealth:	☑ (401 CSL)	
n.	Site conditions present a potential for pollution to waters of the Commonwealth:		
0. 4	Other (describe):		
	Inspection of this project has revealed site conditions which constitute violations of and/or 102 and the Clean Streams Law, the act of June 22, 1937, P.L. 1987, 35 P.S.		apters
	Additional information regarding these violations can be found on the back of	f this report.	
Con	pliance Assistance Measures FOLLOW EROSION CONTROL PLAN.		
Foll	ow-up Inspection will occur on or about (date) 12-30-03	continu	ed 🗌
	C / / /	4	
(Sia	nature of Site Representative) (Date) (Inspector's Signature)	12-9-03 (Date	9)
	(Hispogoria digitatio)	(Date	-,

The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.

 \boxtimes

E & S Control Permit required

Phased Constr.

PAR10D526

NPDES Permit required

Permit #

3630-FM-WQ0090 Rev. 4/2000 COMMONWEALTH OF PENNSYLVANIA Report No. 3 DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION				No. 3
	EARTH DISTURBAN	CE INSPECTION	REPORT	
Tax Parcel #	31-5-19		Inspection D	ate 12/29/03
Certified Mail #	86/8655	,	BUCK	
Project name WO	ODS		Total Project a	rea 139.00/88.
Location JACKSO	NVILLE RD			
Municipality NOR	THAMPTON TWP			
Receiving water(s)	TRIB TO LITTLE NESHAMINY	CREEK Chapter 9	3 designation <u>WW</u>	/F MF
Responsible party	K. HOVANANIAN@NORTHAMF	TON LLC CVA IN	NC	
(name & address)	385 OXFORD VALLEY RD	110 CE	ENTRAL AVE	
	YARDLEY PA 19067	FAIRL	ESS HILLS PA 19030	
Phone	())	
Weather conditions	SUNNY/WARM		Time of Inspection	1:00:00 PM/J:00
Site Representative (name & title) UNKNOWN Inspector ERIC WIGHTMAN				
Type of Inspection ((check only one)	Photographs taken	Yes ⊠ No □	
Routine complete Routine partial Follow-up Complaint Final				
Site Description & 0	Observations 1. FAILURE TO	STABILIZE ALL DISTUR	RBED GROUND ACC	ORDING TO PLAN
72 HOUR NOTICE.	(E,K,L,N) 2. FAILURE TO MA	INTAIN AND INSTALL	SILT FENCE ACC	ORDING TO PLAN
ENTIRE PROJECT(F.L.N). 3. FAILURE TO STAI	BILIZE WITH STRAW	MULCH AND MAIN	AIN SILT FENCE
ACCORDING TO PL	AN AT STREAM CROSSING #1	INVETLANDS.(E,F,K,L,N	I,N) 4 FAILURE I	O MAINTAIN SILT
FENCE BEHIND LO	OT 7-14.(F.L,M,N) 5. FAILURE S	SEDIMENT POLLUTION	OCCURING AT ST	REAM CROSSING
#1(M,N). 6. FAILUR	E SEDIMENT TRAP #1 SHOULD	BE COMPLETED MAIN	TAINED AND STAB	LIZE ACCORDING
TO PLAN.(E,F,K,L,N	(I,N,) 7. FAILURE TO HAVE I	NSPECTION LOGS.(L)	8. FAILURE TO C	BTAIN GENERAL
PERMITS FOR STE	REAM CROSSING ABOVE STR	EAM CROSSING #1.(L)	9. FAILURE TO	COMPLETE AND
STABILIZE ACCORE	DING TO PLAN BASIN A+B.(E,F,K	(,L,M,N,)		
				continued [
Permit an	d Plan Requirements	Type of Activity (chec	ck as many as approp	riate)
	n & Sediment Control Plan required	☐ Pub. Road Constr./Mair	nt. (PRC) 🔲 Pvt. Ro	oad/Residence (PRRS)
	ment Control Plan requested	Res. Subdivision (RSBI	` , —	/Indust. Dev. (CMIN)

CC/RESPONSIBLE OFFICIAL/MUNICIPAL OFFICE/MUNICIPAL ENGINEER/EW/DISTIRCT MANAGER/BCCD FILE/BCCD4.4.61/JG

Non-Phased Constr.

Govmt. Facilities (GOV)

Utilities Facilities (UTL)

Sewer/Water Systems (SWS)

Remediation/Restoration (RRES)

Recreation Facilities (RECF)

Oil/Gas Development (OGD)

Agricul. Activities (AGA)

Silviculture (SILV)

3620 EM WO00002	Day 4/2000
3630-FM-WQ0090a	Kev. 4/2000

Report No.	3



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

EARTH DISTURBANCE INSPECTION REPORT

	LAKIT BIOTOKBAROL INGI LOTTOK KLI OKT			
Insp	ection Findings (check as many as appropriate)	Reference		
a.	No violations observed at this time:	☐ (N/A)		
b.	Failure to develop a written Erosion and Sediment Control Plan:	(102.4)		
C.	Failure to have an Erosion and Sediment Control Plan available on site:	(102.4)		
d.	Failure to submit Erosion and Sediment Control Plan as requested:	☐ (102. 4)		
e.	Failure to implement effective Best Management Practices:	☑ (102.4)		
f.	Failure to maintain effective Best Management Practices:	☑ (102.4)		
g.	Failure to use Special Protection Best Management Practices for discharges to High Quality or Exceptional Value Waters:	(102.4)		
h.	Failure to obtain an NPDES Permit for Stormwater Discharges Associated With a Construction Activity:	☐ (102.5)		
i.	Failure to obtain an Erosion and Sediment Control Permit:	☐ (102.5)		
j.	Failure to demonstrate that alternative Best Management Practices achieve regulatory standards:	[] (102.11)		
k.	Failure to permanently stabilize the earth disturbance site:	⊠ (102.22)		
I.	Failure of earth disturbance activities to comply with permit conditions:			
m.	Failure to prevent sediment or other pollutant discharge into waters of the Commonwealth:	☑ (401 CSL)		
n.	Site conditions present a potential for pollution to waters of the Commonwealth:	☑ (402 CSL)		
Ο.	o.			
Inspection of this project has revealed site conditions which constitute violations of 25 Pa. Code Chapters 92 and/or 102 and the Clean Streams Law, the act of June 22, 1937, P.L. 1987, 35 P.S. §691.1 et seq.				
	Additional information regarding these violations can be found on the back of	this report.		
Con	ppliance Assistance Measures FOLLOW EROSION CONTROL PLAN.			
		continued [
Foll	ow-up Inspection will occur on or about (date) 1-6-03			
C	ertified Mail 12-31-03 Endet	12-31-03		
(Sig	nature of Site Representative) (Date) (Inspector's Sonature)	(Date)		

The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.

3630-FM-WQ0090 Rev. 4/2000

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

Report	No.	4
--------	-----	---

4000 1 111-11	-
THE WITTER	Λ.
	-3
Co continue a A	~

EARTH DISTURBANCE INSPECTION REPORT

Inspection	n Date	
BUCK		
Total Projec	ct area 139.00	
CREEK Chapter 93 designation V	MWF MF	
TON LLC CVA INC		
110 CENTRAL AVE		
FAIRLESS HILLS PA 190	030	
Time of Inspecti	ion 2:00:00 PM	
Inspector ERIC WIGHTM	MAN	
Photographs taken Yes ⊠ No		
Follow-up Complaint C	Final 🗌	
REVIOUSE REPORT COMPLETED. 1. FA	AILURE TO MAINTAIN	
AND INSTALL SWALES #1.2.3.4.9.ACCORDING TO PLAN.E.F.K.L.N. 2. FAILURE TO STABILIZE BASIN A.B.		
1 2 311. 13. 14. 2. 17. 12013 10 01	IABILIZE BASIN A.B.	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L		
	L.N. 3. FAILURE TO	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L	L.N. 3. FAILURE TO SILT FENCE BEHIND	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN	SILT FENCE BEHIND SSING. CROSSING #2	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L A.B. E.F.L.N. 4. FAILURE TO MAINTAIN D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICE	SILT FENCE BEHIND SSING. CROSSING #2	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L A.B. E.F.L.N. 4. FAILURE TO MAINTAIN D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICE	SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L.A.B. E.F.L.N. 4. FAILURE TO MAINTAIN DECLIA ACRE DRIVE WETLAND CROSE ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L 7. FAILURE PROPERTY OF THE PROPERTY	SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L.A.B. E.F.L.N. 4. FAILURE TO MAINTAIN A.B.E.F.L.N. 4. FAILURE TO MAINTAIN A.B.E.F.L.D. CECLIA ACRE DRIVE WETLAND CROSE ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L. 7. FAILURE PROADWAYS.E.F.L.N. 9. FAILURE OUT OUT DE STABILIZED AND SILT FENCE MA	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 SE SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N.	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN A D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L 7. FAILURE POR ROADWAYS.E,F,L,N. 9. FAILURE OUT	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 SE SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N.	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L.A.B. E.F.L.N. 4. FAILURE TO MAINTAIN A.B.E.F.L.N. 4. FAILURE TO MAINTAIN A.B.E.F.L.D. CECLIA ACRE DRIVE WETLAND CROSE ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L. 7. FAILURE PROADWAYS.E.F.L.N. 9. FAILURE OUT OUT DE STABILIZED AND SILT FENCE MA	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 SE SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N.	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN. D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L 7. FAILURE PER ROADWAYS.E,F,L,N. 9. FAILURE OUT JULD BE STABILIZED AND SILT FENCE MAINTAIN SILT FENCE STABILIZE	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N. ZATION.E,F,K,L,N,M. continued	
MAINTAIN BAFFLE IN BASIN A.B.E.F.L.A.B. E.F.L.N. 4. FAILURE TO MAINTAIN A.B.E.F.L.N. 4. FAILURE TO MAINTAIN A.B.E.F.L.D. CECLIA ACRE DRIVE WETLAND CROSE ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L. 7. FAILURE PROADWAYS.E.F.L.N. 9. FAILURE OUT OUT DE STABILIZED AND SILT FENCE MA	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N. ZATION.E,F,K,L,N,M. continued	
MAINTAIN BAFFLE IN BASIN A,B.E,F,LA,B. E,F,L,N. 4. FAILURE TO MAINTAIN DECELLA ACRE DRIVE WETLAND CROSE ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L 7. FAILURE PROADWAYS.E,F,L,N. 9. FAILURE OUT DISTURBED AND SILT FENCE MAINTAIN SILT FENCE STABILIZED AND TENCE STABILIZED AND SILT FENCE STABILIZED S	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N. ZATION.E,F,K,L,N,M. continued	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN. D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICE ISPECTION LOGS.L 7. FAILURE PER EROADWAYS.E,F,L,N. 9. FAILURE OUT JULD BE STABILIZED AND SILT FENCE MAINTAIN SILT FENCE STABILIZE Type of Activity (check as many as appr	L.N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N. ZATION.E,F,K,L,N,M. continued ropriate)	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN. D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICI ISPECTION LOGS.L 7. FAILURE PER ECOADWAYS.E,F,L,N. 9. FAILURE OUT INDICATE BY ESS NOT MAINTAIN SILT FENCE STABILIZED Type of Activity (check as many as appr D Pub. Road Constr./Maint. (PRC) D PVE Res. Subdivision (RSBD) D Con	L.N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N,M. Continued Tropriate) t. Road/Residence (PRRS)	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN. D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICI ISPECTION LOGS.L 7. FAILURE PRODUCTION FOR SOIL 7. FAILURE PRODUCTION FOR STABILIZED AND SILT FENCE MAINTAIN SILT FENCE STABILIZED AND S	L,N. 3. FAILURE TO SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N. ZATION.E,F,K,L,N,M. continued ropriate) t. Road/Residence (PRRS) comm./Indust. Dev. (CMIN)	
MAINTAIN BAFFLE IN BASIN A,B.E,F,L A,B. E,F,L,N. 4. FAILURE TO MAINTAIN. D CECLIA ACRE DRIVE WETLAND CROS E ALL DISTURBED SOIL 72 HOUR NOTICI ISPECTION LOGS.L 7. FAILURE PER ROADWAYS.E,F,L,N. 9. FAILURE OUT INDICATE BY THE STABILIZED AND SILT FENCE MAINTAIN SILT FENCE STABILIZED Type of Activity (check as many as approximately approxim	SILT FENCE BEHIND SSING. CROSSING #2 E SEED AND STRAW POSSIBLE WETLAND OF CONSTURCTION AINTAINED.E,F,K,L,N,M. Continued ropriate) t. Road/Residence (PRRS) omm./Indust. Dev. (CMIN) ecreation Facilities (RECF)	
	CREEK Chapter 93 designation Notes Property Complaint Complete Property Complete Com	

3630-FM-WQ0090a Rev. 4/2000



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

Report No.

EARTH DISTURBANCE INSPECTION REPORT

laane	Reference				
inspe	ection Findings (check as many as	appropriate)		☐ (N/A)	
_	No violations observed at this time:		steel Disco	□ (402.4)	
b.	Failure to develop a written Erosion			☐ (102.4)	
C.	Failure to have an Erosion and Sedi			☐ (102.4)	
d.	Failure to submit Erosion and Sedin		•	☐ (102.4)	
e.	Failure to implement effective Best	Management Prac	tices:		
f.	Failure to maintain effective Best M	anagement Practic	ces:	⊠ (102.4)	
g.	Failure to use Special Protection Be Quality or Exceptional Value Water		ractices for discharges to High	☐ (102. 4)	
h.	Failure to obtain an NPDES Permit Construction Activity:	for Stormwater Dis	scharges Associated With a	☐ (102.5)	
i.	Failure to obtain an Erosion and Se	diment Control Per	mit:	(102.5)	
j.	Failure to demonstrate that alternatistandards:	ive Best Managem	ent Practices achieve regulatory	☐ (102.11)	
k.	Failure to permanently stabilize the	earth disturbance	site:	⊠ (102.22)	
I.	Failure of earth disturbance activities	es to comply with p	ermit conditions:	☑ (402 CSL)	
m.				☑ (401 CSL)	
n.	Site conditions present a potential f	or pollution to wate	ers of the Commonwealth:	☑ (402 CSL)	
0.	Other (describe):				
\boxtimes			ions which constitute violations of June 22, 1937, P.L. 1987, 35 P.S		
	Additional information rega	arding these viola	tions can be found on the back o	f this report.	
Compliance Assistance Measures FOLLOW EROSION CONTROL PLAN. SPOKE TO JEFF HOVAN. FOREMAN					
		,		continued [
Foll	ow-up Inspection will occur on or	about (date) <u>6-3</u>	3-04		
	L.N.		Sath		
<u>(2:</u>	ertitud mil	5-21-04	with the	<u>5-21-04</u>	
(Sig	nature of Site Representative)	(Date)	(Inspector's Signature)	(Date)	

The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

EARTH DISTURBANCE INSPECTION REPORT

Continuation Sheet (check appropriate box)	
Site Description and Observations	Compliance Assistance Measures
Site Description & Observations 11. FAILURE STREAM	CROSSING #1 SHOULD HAVE BANKS REGRADED AND
STABILIZE WITH NORTH AMERICAN GREEN 125.E,F,I	K.L.N.M. 12. FAILURE INLETS BEHIND LOTS #10,11.
SHOULD BE PROTECTED ACCORDING TO PLAN.E.F.K	LLN,M. POSSIBLE STATE AND FEDERAL
WETI AND PERMIT VIOLATION.	
	<u> </u>
	<u> </u>

3630-FM-WQ0090 Rev. 4/2000

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

Report No.	5	

BUREAU OF WATER QUALITY PROTECTION
EARTH DISTURBANCE INSPECTION REPOR

EARTH DISTURBANCE INSPECTION REPORT				
Tax Parcel # 31-5-19	Inspection Date 5/27/04			
Certified Mail # 6569/6 56 9 652	BUCK			
Project name WOODS	Total Project area _139.00			
Location JACKSONVILLE RD				
Municipality NORTHAMPTON TWP				
Receiving water(s) TRIB TO LITTLE NESHAMINY C	REEK Chapter 93 designation WWF MF			
Responsible party K. HOVANANIAN@NORTHAMP	TON LLC CVA INC			
(name & address) 385 OXFORD VALLEY RD	110 CENTRAL AVE			
YARDLEY PA 19067	FAIRLESS HILLS PA 19030			
Phone ()	()			
Weather conditions SUNNY WARM	Time of Inspection 1:00:00 PM			
Site Representative (name & title) DELL	Inspector ERIC WIGHTMAN			
Type of Inspection (check only one)	Photographs taken Yes ⊠ No □			
Routine complete ⊠ Routine partial ☐ F	Follow-up ⊠ Complaint ☐ Final ☐			
Site Description & Observations VIOLATION ON P	REVIOUSE REPORT COMPLETED.1,3,3,4,6,11. 2. FAILURE			
TO STABILIZE BASIN A,B. ACCORDING TO PLAN.E,I	F,K,LN. 5. FAILURE TO STABILIZE ALL DISTURBED SOIL 72			
HOUR NOTICE SEED AND STRAW MULCH.E.F.K.L.I	N 7. FAILURE POSSIBLE WETLAND VIOLATION.L,N,M. 8.			
FAILURE SEDIMENT ON ROADWAYS.E,F,L,N. 9	FAILURE OUT OF CONSTURCTION SEQUENCE L, N. 9.			
FAILURE TOP SOIL PILE SHOULD BE STABILIZED	O AND SILT FENCE MAINTAINED.E,F,K,L,N. 10. FAILURE			
PROTECTION OF STREAM CROSSINGS NOT MAIN	TAIN SILT FENCE STABILIZATION.E,F,K,L,N,M. 1a. failure to			
maintain basin spillway a,b.E,F,K,L,N. 2b.failure to ma	aintain,stabilize endwall 286,1826 .E,F,K,L,N. 3b.failure to install			
and maintain silt fence behind lots10,11., lot 17 wetland	d line to both side of the wetland crossing lot 18. Man hole lid 47			
south of lot 17 to protect wetlands, pump station silt f	fence. silt fence at box culvert should be repaired.E,F,L,N. 4b.			
failure to install inlet protection discharging to stream. E.	,F,L,N,M.			
	continued [
Permit and Plan Requirements	Type of Activity (check as many as appropriate)			
Y N	Type of Address (oncon do many do appropriato)			
	☐ Pub. Road Constr./Maint. (PRC) ☐ Pvt. Road/Residence (PRRS)			
☐ ☒ Erosion & Sediment Control Plan requested	Res. Subdivision (RSBD)			
□ ☑ E & S Control Permit required	Govmt. Facilities (GOV) Recreation Facilities (RECF)			
☑ □ NPDES Permit required	☐ Utilities Facilities (UTL) ☐ Agricul. Activities (AGA)			
	☐ Sewer/Water Systems (SWS) ☐ Oil/Gas Development (OGD)			
Permit # PAR10D526	☐ Remediation/Restoration (RRES) ☐ Silviculture (SILV)			



Report No.	_5



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

EARTH DISTURBANCE INSPECTION REPORT

Inspection Findings (check as many as appropriate) Reference				
a.	No violations observed at this time:	☐ (N/A)		
b.	Failure to develop a written Erosion and Sediment Control Plan:	☑ (102.4)		
	Failure to have an Erosion and Sediment Control Plan available on site:	(102.4)		
C.		(102.4)		
d.	Failure to submit Erosion and Sediment Control Plan as requested:	_ ` '		
e.	Failure to implement effective Best Management Practices:	⊠ (102.4)		
f.	Failure to maintain effective Best Management Practices:	⊠ (102.4)		
g.	Failure to use Special Protection Best Management Practices for discharges to High Quality or Exceptional Value Waters:	☐ (102. 4)		
h.	Failure to obtain an NPDES Permit for Stormwater Discharges Associated With a Construction Activity:	☐ (102.5)		
í.	Failure to obtain an Erosion and Sediment Control Permit:	(102.5)		
j.	Failure to demonstrate that alternative Best Management Practices achieve regulatory standards:	☐ (102.11)		
k.	Failure to permanently stabilize the earth disturbance site:	⊠ (102.22)		
1.	Failure of earth disturbance activities to comply with permit conditions:	☑ (402 CSL)		
m.	Failure to prevent sediment or other pollutant discharge into waters of the Commonwealth:	⊠ (401 CSL)		
n.	Site conditions present a potential for pollution to waters of the Commonwealth:	☑ (402 CSL)		
Ο.	Other (describe):			
	Additional information regarding these violations can be found on the back of	this report.		
Compliance Assistance Measures FOLLOW EROSION CONTROL PLAN. SPOKE TO DELL. HOV. FOREMAN JIM				
TONY CVA CONST. MIKE KANE TWP ENGINEER				
		continued [
Foli	ow-up Inspection will occur on or about (date) 6-8-04			
ري (htied mil 6-1-04 Ethelin	6-1-04		
(Sig	nature of Site Representative) (Date) (Inspector's Signature)	(Date)		



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

EARTH DISTURBANCE INSPECTION REPORT

Continuation Sheet (check appropriate be	ox)
☐ Site Description and Observations	Compliance Assistance Measures
Site Description & Observations 5b.	failure to install pumping bag correctly at pump station sediment pollution
occuring.E.F.L.N.M. 6b. failure to revise	plan for additional disturbance.B,L,N,M 7B, SEDIMENT WHICH ENTERED
STREAM AT CROSSING SHOULD BE RE	EMOVED TO ORIGINAL STREAM GRADE, E,F,L,N,M. 12. FAILURE INLETS
BEHIND LOTS #10,11. SHOULD BE PRO	DIFFICIED ACCORDING TO PLAN.E,F,K,L,N,M. POSSIBLE STATE
AND FEDERAL WETLAND PERMIT VIOL	ATION.

3630-FM-WQ0090 Rev. 4/2000

Permit #

PAR10D526

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATER QUALITY PROTECTION

Report	No.
--------	-----

BUREAU OF WATER QUALITY PROT
EARTH DISTURBANCE INSPEC

_	EARTH DISTURBANG	CEI	NSPECTIO	N KEPU	KI		
Tax Parcel #	31-5-19			i	nspecti	ion Date	5/13/04
Certified Mail # 6651/6668				BUCK			
Project nameWO	ODS			To	tal Proj	ect area	139.00
Location JACKSOI	NVILLE RD						
Municipality NOR	THAMPTON TWP						
Receiving water(s)	TRIB TO LITTLE NESHAMINY C	REE	Chapter	93 design	ation	WWF MI	F
Responsible party	K. HOVANANIAN@NORTHAMP	TON	LLC CVA	INC			
(name & address)	385 OXFORD VALLEY RD		110	CENTRAL	AVE_		
	YARDLEY PA 19067		FAI	RLESS HILL	LS PA 1	9030	
Phone	())			
Weather conditions	SUNNY WARM			Time of	f Inspe	ction 2:	:00:00 PM
Site Representative	(name & title) jeff		Insp	pector ER	IC WIGH	TMAN	
Type of Inspection (` <u> </u>		otographs take			No 🗌	. 🗆
Routine complete	• —		⁄-up □	Comple			al 🗌
-	Observations VIOLATION ON PR						
	LES #1,2,3,4,9,ACCORDING TO						•
	LAN.E.F.K.LN. 3. FAILURE TO						
	AROUND RISER PIPE IN BASIN A	-					
-	CULVERT #1 BOTH SIDE OF RE						
	F,L,N. 5. FAILURE TO STABILIZE						
	6. FAILURE TO PROVIDE IN						LE WETLAND
	8. FAILURE SEDIMENT ON R FAILURE TOP SOIL PILE SHOU						
	The state of the s						
IV. FAILURE PROTE	ECTION OF STREAM CROSSING	is NO	I MAINTAIN SI	LIFENCE	STADIL	.IZATION.	C,F,K,L,N,WI.
						с	ontinued 🗌
Permit an	d Plan Requirements	Туре	e of Activity (ch	neck as mar	ny as ap	opropriate)	
Y N							
	n & Sediment Control Plan required		Pub. Road Constr./N	` ,			sidence (PRRS)
	ment Control Plan requested	×	Res. Subdivision (R	•			st. Dev. (CMIN)
☐ ☑ E&S Control F	·		Govmt. Facilities (G	-	_		acilities (RECF)
NPDES Permit	_		Utilities Facilities (U	•		Agricul. Activ	
⊠ Phased	d Constr.		Sewer/Water Syster	ns (SWS)		Oil/Gas Deve	elopment (OGD)

Remediation/Restoration (RRES)

Silviculture (SILV)

Report	No.	6

3630-FM-WQ0090 Rev. 4/2000	COMMONWEALTH OF PENNS ILVANIA	Kep
	DEPARTMENT OF ENVIRONMENTAL PROTECTION	-
	BUREAU OF WATER QUALITY PROTECTION	
	EARTH DISTURBANCE INSPECTION REPOI	₹T
	EARTH BIOTOND AND ENTIRE OF	• •

	CL INSPECTION INLPOINT				
Tax Parcel # 31-5-19	Inspection Date 6/10/04				
Certified Mail # 8365/8341	BUCK				
Project name WOODS	Total Project area 139.00				
Location JACKSONVILLE RD					
Municipality NORTHAMPTON TWP					
Receiving water(s) TRIB TO LITTLE NESHAMINY O	CREEK Chapter 93 designation WWF MF				
Responsible party K. HOVANANIAN@NORTHAMP	TON LLC CVA INC				
(name & address) 385 OXFORD VALLEY RD	110 CENTRAL AVE				
YARDLEY PA 19067	FAIRLESS HILLS PA 19030				
Phone ()	()				
Weather conditions SUNNY WARM	Time of Inspection 3:30:00 AM				
Site Representative (name & title) DELL shelton	Inspector ERIC WIGHTMAN				
Type of Inspection (check only one)	Photographs taken Yes ☐ No ⊠				
	Follow-up ⊠ Complaint ☐ Final ☐				
• —	VIOLATION ON PREVIOUSE REPORT				
•					
COMPLETED.12.7b,5b,4b,3b,2b,1a,10,9,8,,5,2,6b.	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N,M.				
•					
•					
•					
•					
•					
•	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N,M.				
•					
•	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N.M.				
COMPLETED.12.7b,5b,4b,3b,2b,1a,10,9,8,.5,2,6b.	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N,M.				
COMPLETED.12.7b,5b,4b,3b,2b,1a,10,9,8,.5,2,6b. Permit and Plan Requirements	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N.M. continued				
Permit and Plan Requirements Y N	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N.M. continued Type of Activity (check as many as appropriate)				
Permit and Plan Requirements Y N M M Written Erosion & Sediment Control Plan required	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N.M. continued Type of Activity (check as many as appropriate) Pub. Road Constr./Maint. (PRC) Pvt. Road/Residence (PRRS)				
Permit and Plan Requirements Y N M G Written Erosion & Sediment Control Plan required Erosion & Sediment Control Plan requested	7. FAILURE POSSIBLE WETLAND VIOLATION.L,N,M. continued □ Type of Activity (check as many as appropriate) □ Pub. Road Constr./Maint. (PRC) □ Pvt. Road/Residence (PRRS) □ Res. Subdivision (RSBD) □ Comm./Indust. Dev. (CMIN)				
Permit and Plan Requirements Y N M Grosion & Sediment Control Plan required Erosion & Sediment Control Plan requested E & S Control Permit required	Type of Activity (check as many as appropriate) □ Pub. Road Constr./Maint. (PRC) □ Pvt. Road/Residence (PRRS) □ Res. Subdivision (RSBD) □ Comm./Indust. Dev. (CMIN) □ Govmt. Facilities (GOV) □ Recreation Facilities (RECF)				

CC/RESPONSIBLE OFFICIAL/MUNICIPAL OFFICE/MUNICIPAL ENGINEER/EW/DISTIRCT MANAGER/BCCD FILE/BCCD4-1-31/JG

3630-FM-WQ0090a Rev. 4/2000


Report No.	6


COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION **BUREAU OF WATER QUALITY PROTECTION**

EARTH DISTURB	ANCE	INSPECTI	ON REPORT
	ANCE	11426 EC 11	OIA IVELOUS

	EARTH DISTURBANCE INSPECTION REPORT		>
Inspe	ection Findings (check as many as appropriate)	Reference	
a.	No violations observed at this time:		
b.	Failure to develop a written Erosion and Sediment Control Plan:	(102. 4)	
C.	Failure to have an Erosion and Sediment Control Plan available on site:	(102. 4)	
d.	Failure to submit Erosion and Sediment Control Plan as requested:	(102. 4)	
e.	Failure to implement effective Best Management Practices:	(102. 4)	
f.	Failure to maintain effective Best Management Practices:	(102. 4)	
g.	Failure to use Special Protection Best Management Practices for discharges to High Quality or Exceptional Value Waters:	☐ (102. 4)	
h.	Failure to obtain an NPDES Permit for Stormwater Discharges Associated With a Construction Activity:	(102.5)	
i.	Failure to obtain an Erosion and Sediment Control Permit:	(102.5)	
j.	Failure to demonstrate that alternative Best Management Practices achieve regulatory standards:	[] (102.11)	(
k.	Failure to permanently stabilize the earth disturbance site:	(102.22)	(
I.	Failure of earth disturbance activities to comply with permit conditions:	(402 CSL)	•
m.	Failure to prevent sediment or other pollutant discharge into waters of the Commonwealth:	☐ (401 CSL)	
n.	Site conditions present a potential for pollution to waters of the Commonwealth:	(402 CSL)	
0.	Other (describe):		
	Inspection of this project has revealed site conditions which constitute violations o 92 and/or 102 and the Clean Streams Law, the act of June 22, 1937, P.L. 1987, 35 P.S		apters
	Additional information regarding these violations can be found on the back of	this report.	
Com	pliance Assistance Measures follow erosion control plan.		
····			
	· · · · · · · · · · · · · · · · · · ·		
			1
		continue	
Follo	ow-up Inspection will occur on or about (date) <u>routine</u>	continue	ea (<u>()</u>
C.	ertifical mail 6-17-04 Establish	6-17-04	
	nature of Site Representative) (Date) (Inspector's Signature)	(Date)

The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.







"ericwightman@bucks conservation.org" <ericwightman

To: Chuck Schadel/R3/USEPA/US@EPA

cc:

Subject: woods at northampton k.hovnanian

10/08/2004 11:00 AM Please respond to ericwightman

Location to Woods at Northampton site Bucks County PA

Rte 276 to rte 611 north to Blair mill rd (N.east) take right onto County Line Rd (S. east). left onto jacksonville rd (N.east)

ADC map map page 35/C,#1

Address Jacksonville Rd and almshouse Rd Bucks County PA

mail2web - Check your email from the web at http://mail2web.com/ .

EPA	Washingto	ronmental Protection Agency n, D.C. 20460 e Inspection Report					
Section A: National Data System Coding (i.e., PCS)							
Transaction Code NP		spection Type Inspector SCHADEL	Facility Type construction				
	(building) compliance (performing site re Havnanian as of this inspectio						
Inspection Work DaysFac	cility Self Monitoring Evaluation	n Rating B1 QA	Reserved				
	Section	B: Facility Data					
Name and Location of F The Woods at No North Hampton Towns	_ =	entry Time/Date ~9:30 am / October 14 2004	Feb 6, 2001				
		Exit Time/Date: ~ 12:30 pm / Oct 14 , 2004	Permit Expiration Date: Feb 6, 2006				
On-Site Representative(s)/Title(s)/Affiliation/Phone and Fax Number(s) Delmar Shelton(215) 495-4230 K. Hovnanian Homes Other Facility Data (Developer/Contractor/Sub-Contractor/Engineer) CVA is the e&s inspecting sub-contractor (215) 946-4500							
Name, Address of Per Official/Title/Affiliation Cecelia Recklitis 117 Jacksonville Rd Ivyland, PA 18974	mittee n/Phone and Fax Number						
Tel. (215) 355.7277	Contacted No						
Section C: A	Areas Evaluated During Ir	spection (Check only those	e areas evaluated)				
X Permit	Flow Measurement	Operations &	CSO/SSO (Sewer				
X Records/Reports	Self-Monitoring	Sludge	Pollution Prevention				
X Facility/ Site Review	Compliance Schedules	Pretreatment	Multimedia				
X Discharge	Laboratory	X Storm Water/SWPPP	Other: Sampling				
Section D: Summary	of Findings/Comments (A	Attach additional sheets of	narrative and checklist as				
See Attachment	•						
Name(s) and Signature			Date) ,				
truck Shadal	. OSEPA Regin IV (215)814-5761	11 30 04				
Signature of Reviewer	Agency/Office		Date				
EPA Form 3560-3 (Re	v 9-94) Previous editions	are obsolete					

NPDES Industrial Storm Water Worksheet (Construction)

			ACILITY LOCATION IN	FORMA	TION			
GPS Coordinates	Lati	tude	N 40°, 13′, 15′′		Longit	ude	W 75°, 03′, 3	0.5 ′′
Receiving Water(s) or MS4	eceiving Water(s) or MS4 2 tribs to Little Neshaminy							
Total site area acres & disturbed acres	~140	~88	Ground- Breaking Date		ing 2001 n NOI)	Fin	al Stabilization Date	Fall 2002 (on NOI)
Copy of NOI/Permit on site	N	0	Date of NOI Discharge to 303(d) Y or listed waters		Y or N			
Permit #		PAR1	0 D526			() () () () () () () () () ()		

BASIC SWPPP INFORMATION

	Present in storm water management plan ? (Y or N)	Does NPDES permit require items in plan (Y or N)
Plan & attachments available, current & complete	Yes	yes
Contractor & Subcontractor certification statement	No	yes
Drainage pattern(s)	Yes	yes
Storm water discharge location(s)	Yes	yes
Name of receiving water(s) / wetland(s) or MS4	Yes	yes
Location & description of BMPs	Yes	yes
BMP design computations	Yes	yes
Any requirements for post construction control	partial	Yes
Date when construction activity temporarily or permanently ceased on a portion of the site	No	no
Date when stabilization measures are initiated on site (should be within 14 days after construction has ceased)	No	no
Records of Operator Inspections	Only from 1/04 to 5/04	yes
Rainfall records	No	no
Permittee site inspections within 24 hours at the end of a storm event	No	yes
Appropriate actions taken within 7 days of identifying BMP deficiency	No	yes
(Other)		
(Other)		

General Site Notes

E &S contractor is not keeping inspection logs current

OUTFALL, STORM WATER DISCHARGE & RECEIVING WATERS OBSERVATIONS				
Describe Discharge location / mixing zone at receiving waters	Stream swollen and turbid. However, clearly there is a deeper orange "ribbon" caused by the discharge form the site.			
:				
Information about receiving surface water:	WWF, MF First order streams on property			
·				
•				
Non-storm, water discharge	None observed.			
Non-storm water discharge observed	None abserved.			
Other discharges or potential discharges off-site (not permitted)				
permitted)				
· · · · · · · · · · · · · · · · · · ·				


Name of Inspected Site: The Woods at North Hampton

(Describe observations made of erosion, sediment transport, material handling activities, storage locations, ground cover, and/or BMPs being implemented/maintained at the Site)


Notes: Observations were made during the inspection of October 14, 2004				
Pollutant of concern: sediment	Person informed of observation : Delmar Shelton (215) 495-4230			
Describe persons action taken during inspection, in response to observation:				
Picture Identifiers for attached map: Please refer to Attached photo and attached map of the construction site				
Location	Photo #	Location	Photo #	
			1	
		<u> </u>		
Location	Photo #	Location	Photo #	
Location	Photo #	Location	Photo #	
Location	- 1010#	Location	- 11010#	
			1	
Location	Photo #	Location	Photo #	
]	
Location	Photo #	Location	Photo #	
	· .		<u> </u>	
Location	Photo #	Location	Photo #	
Location				
·			1	
Location	Photo #	Location	Photo #	
	_			
Location	Photo #	Location	Photo #	
Location	1 11010 #	Location	1 11010 #	
	1			
Location	Photo #	Location	Photo #	
			1	

Photo Log for
Oct 14, 2004 NPDES Inspection of
the Woods at North Hampton construction site
Developer:
Hovnanian Pennsylvanian, Inc.

Inspector: C Schadel USEPA Region III



DSC02869 photo is a view of drums and bags stored at location A



DSC02875 photo is a closer view of the drums viewed in DSC02869



DSC02870 photo is a view of curing compound stored at location A




DSC02871 photo is a close view of view of bags with Calcium Chloride printed on the outside, stored at location A




DSC02872 photo is a more wider view of the bags in DSC02871.



DSC02873 photo is a view of casting forms stored at location A



DSC02874 photo is a view of curing compound stored at location A




DSC02876 is a view of lot #34.



DSC02877 is a view of the north side of Sienna Circle (approx location is lot #48), west of Copperleaf Court.




DSC02878 is a view of the south side of Sienna Circle (approx location is lot #48), west of Copperleaf Court.




DSC02879 is a view of the south side of Sienna Circle (approx location is lot #31), west of Copperleaf Court.



Circle (approx location is lot #30), west of Copperleaf Court.



DSC02881 is a view while facing lot #30. Silt fence is in disrepair.




DSC02882 is a view of Copperleaf, while standing in Sienna Circle. Mud tracks in road.



DSC02883 is a view of the sidewalk along Sienna Circle at lot 43. Soil not stabilized



DSC02884 is a view of the eastern portion of Basin B.



DSC02885 is a closer view of the eastern portion of Basin B. Minor erosion occurring on the far slope.



DSC02886 is a view of the baffles in Basin B.




DSC02887 is a view of the western portion of Basin B.




DSC02888 is a view of the area along the western side of Basin B.



DSC02889 is a closer view of the area along the western side of Basin B. Soil not fully stabilized.




DSC02890 is a view of the area along the western side of Basin B. Erosion scars present.



DSC02891 is a view of the area along the western side of Basin B. Erosion scars present.



DSC02892 is a view of a swale which leads to Basin B.



DSC02893 is a view of the western portion of Basin A.



DSC02894 is a closer view of the western portion of Basin A.




DSC02895 is a view of the middle portion of Basin A. Baffle present



DSC02896 is a another view of the middle portion of Basin A. Baffle present



DSC02897 is a view of the eastern portion of Basin A. Baffle present



DSC02898 is another view of the eastern portion of Basin A. Baffle present



DSC02899 is a view of the stock piles, approximately located between Lots 40 and 46.



DSC02900 is a view of the stock piles, approximately located behind Lot 39.



DSC02901 is a view of the stock piles, approximately located behind Lot 40.




DSC02902 is a view of the stock piles, approximately located behind Lot 39.




DSC02903 is a view of the stock piles, approximately located behind Lot 40.



DSC02904 is a view of the curb on Sienna Circle, approximate location is in front of Lots #2 & #3.



DSC02905 is a view of the curb on Sienna Circle, approximate location is in front of Lot #2.



DSC02906 is a view of the curb on Sienna Circle, approximate location is in front of Lot #2.



DSC02907 is a view of the curb on Sienna Circle, approximate location is in front of Lot #3. Soil in street.




DSC02908 is a view of the curb on Cecelia Acres Drive, approximate location is in front of Lot #21.




DSC02909 is a view of the curb on Cecelia Acres Drive, approximate location is in front of Lot #16. Inlet protection not present. Inlet drains to surface water.




DSC02911 is a closer of DSC02909




DSC02910 is a view of the curb on Cecelia Acres Drive, approximate location is in front of Lot #16. Inlet protection is present, but clogged. Inlet drains to surface water.



DSC02912 is a view of the silt fence at stream crossing at Lot #16 on Cecelia Acres Drive.



DSC02913 is a view of a turbid discharge, downstream of the inlets identified in DSC02909 and DSC02910



DSC02914 is a view of the silt fence at stream crossing at Lot #16 on Cecelia Acres Drive.



DSC02915 is a view of the silt fence at stream crossing at Lot #16 on Cecelia Acres Drive.



DSC02916 is a view of the surface water upstream of Cecelia Acres Drive and the inlets identified in DSC02909 and DSC02910



DSC02917 is a view of aquatic plants in the surface water upstream of Cecelia Acres Drive and the inlets identified in DSC02909 and DSC02910




DSC02918 is a view of the silt fence at Lot #17 on Cecelia Acres Drive.




DSC02919 is a view of the curb along Cecelia Acres Drive, Lots 17 and 80.



DSC02920 is a view of the curb along Cecelia Acres Drive, Lots 51, 52 and 53. and 80.



DSC02921 is a view of a grassed area, approximate location is behind Lots 17 and 80.




DSC02922 is a view of a stabilized stock pile with silt fence at perimeter, approximate location is between Lots 79 and 80.



DSC02923 is a view of a Lots 78 and 77.



DSC02924 is a view of Cecelia Acres Drive and Lot 92. Stock pile on Lot 92 is stabilized.



DSC02925 is an accidental photo




DSC02926 is a view of a path for storm water behind Lots 78



DSC02927 is a view of a path for storm water behind Lot 78



DSC02928 is a view of a the area behind Lot 78



DSC02929 is a view of a Lots 76




DSC02930 is a view of the curb along a Lots 76 to 73.



DSC02931 is a view of the curb along a Lots 91 to 88.




DSC02932 is a view of a stabilized stock pile at Lot 91.



DSC02933 is a view of the curb along Cecelia Acres Drive, approximate location is Lot 73.



DSC02934 is a view of the super silt fence at the stream crossing between Lots #87 and 70 on Cecelia Acres Drive.



DSC02935 is a view of the stream at the stream crossing between Lots #87 and 70 on Cecelia Acres Drive.



DSC02936 is a view of the stream at the stream crossing between Lots #87 and 70 on Cecelia Acres Drive.




DSC02937 is a closer view of the DSC02936



 ${\tt DSC02938} \ \ {\sf is\ a\ view\ of\ the\ stream,\ upstream\ from\ DSC02936}$



DSC02939 is a view of the stream, upstream from DSC02936, on the north side of Cecelia Acres Drive




DSC02940 is another closer view of the DSC02936



DSC02941is another closer view of the DSC02936



DSC02942 is a view of the stream and silt fence in disrepair, on the south side of Cecelia Acres Drive



DSC02943 is a view of the stream, on the south side of Cecelia Acres Drive



DSC02944 is a view of the stream, on the south side of Cecelia Acres Drive



DSC02945 is a view of the stream, on the south side of Cecelia Acres Drive




DSC02946 is a view of sitl fence along Lot #86




DSC02947 is a view of silt fence along Lot #86



DSC02948 is a view of sitl fence along Lot #86



DSC02949 is a view of silt fence along northern side of Lot #86. Filter fabric in disrepair.



DSC02951 wider view of DSC02949




DSC02952 is a view of the trench which is connected to the opening in the silt fence identified DSC02949



DSC02953 is a view of Lot #68, that is being drained through the trench identified in DSC02952. Water is not being filtered before reaching



DSC02954 is a view of part of Lot # 68 and Lot #67.




DSC02955 is a view of part of Lot # 61, 62 and 63




DSC02956 is a view of Lot # 66 and Lot #67



DSC02957 is a view of Lot #63



DSC02958 is a view of part of soil not stabilized, approximate location is Lot # 63



DSC02959 is a view of soil partially stabilized, approximate location is Lot # 93




DSC02960 is a view of part a swale, approximate location is Lot # 64




DSC02961 is a view of part a swale, approximate location is Lot # 64




DSC02962 is a view of erosion at Basin D.




DSC02963 is a closer view of erosion at Basin D.



DSC02964 is a view of erosion at Basin D.



DSC02965 is a view of erosion at Basin D.



DSC02966 is a view of erosion at Basin D.



DSC02967 is a view of erosion at Basin D.



DSC02968 is a view of erosion at Basin D.




DSC02969 is a view of erosion at Basin D.




DSC02970 is a view of Basin D.



DSC02971 is a view of Basin D.



DSC02972 is a view of Basin D



DSC02973 is a view of the outfall from Basin D



DSC02975 is a view of sediment in wetland area which receives discharges from Basin D.



DSC02976 is a view of a background area adjacent to the area viewed in in DSC02975




DSC02977 is a view of sediment in wetland area which receives discharges from Basin D



DSC02978



DSC02979 is a view of sediment in wetland area which receives discharges from Basin D



DSC02980 is a view of sediment in wetland area which receives discharges from Basin D



DSC02981 is a view of sediment in wetland area which receives discharges from Basin D




DSC02982 is a view of a background area adjacent to the area viewed in in DSC02981



DSC02983 is a view of discarded silt fence approximate location is Lot #56.



DSC02984 is a view of discarded silt fence, approximate location is Lot #56.



DSC02985 is a view of discarded silt fence, approximate location is Lot #56.



DSC02986 is a view of discarded silt fence, approximate location is Lot #56.




DSC02987 is a view of silt fence at the stream crossing between Lot #82 and Lot #53, on the northern side of Cecelia Acres Drive.




DSC02988 is a view of silt fence at the stream crossing between Lot #82 and Lot #53, on the northern side of Cecelia Acres Drive.




DSC02989 is a view of silt fence at the stream crossing between Lot #82 and Lot #53, on the southern side of Cecelia Acres Drive.



DSC02990 is a view of silt fence at the stream crossing between Lot #82 and Lot #53, on the southern side of Cecelia Acres Drive.



DSC02991 is a view of an inlet that drains directly to the stream between Lot #82 and Lot #53, on the southern side of Cecelia Acres Drive. Inlet protection not on inlet.



DSC029902 is a view of an inlet that drains directly to the stream between Lot #82 and Lot #53, on the southern side of Cecelia Acres Drive. This inlet drains to Basin C.

1-5511

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICTION OF ENGINEERS
WANAMAKER BUILDING, JOU PENN SQUARE EAST
PHILADELPHIA, PENNSYLVANIA 19107-3390

Regulatory Branch Surveillance and Enforcement Section

SUBJECT:

CENAP-OP-R-200400415 Violation CENAP-OP-R-200100167-PASPGP-2

PADEP #: E09-828

CENAP-OP-R-200000350-JD

AUG 2 5 2004

Mr. Dennis P. LaRosa K. Hovnanian Companies of Pennsylvania, Incorporated Makefield Executive Quarters 301 Oxford Valley Road, Suite 84 Yardley, Pennsylvania 19067

Dear Mr. LaRosa:

This letter is written with regard to our letter to Mr. Scott E. Bush, Exponent, Exton, Pennsylvania, dated October 29, 2002. The letter authorized K. Hovnanian Companies, Inc., Yardley, Pennsylvania, to perform regulated work under authority of the Pennsylvania State Programmatic General Permit 2 (CENAP-OP-R-200100167-PASPGP-2). The regulated work is associated with construction of "The Woods at Northampton," a residential development located in Northampton Township, Bucks County, Pennsylvania. The Pennsylvania Department of Environmental Protection (PADEP) authorization number is #E09-828. This letter is also written with regard to our Cease and Desist letter of July 27, 2004.

As a result of information provided to this office on May 27, 2004 by the Bucks County Conservation District (BCCD), New Britain, Pennsylvania, and observations made on June 2 and June 22, 2004 during on site inspections by Mr. Michael Green of this office, it was determined that work had been performed in noncompliance with Conditions and Special Conditions of the above referenced permit. K. Hovnanian Companies, Inc. was notified of the noncompliance issues in our letter dated July 27, 2004.

The items of noncompliance include:

- a. Special Condition "1" states: "All work performed in association with the above noted project shall be conducted in accordance with the project plans identified as 'Grading Plan...', prepared by Showalter & Associates, dated March 13, 2000, last revised December 2, 2001, and April 10, 2002, sheets 16 through 23 of 72." Work was performed in noncompliance with the approved plans;
- b. Special Condition "3" states: "Any deviation in construction methodology or project design from that shown on the above noted drawings must be approved by this office, in writing, prior to performance of the work. All modifications to the above noted project plans shall be approved, in writing, by this office. No work shall be performed prior to written approval of this office." The above noted approved drawings were not modified; and

c. Condition "B3" of the PASPGP-2 states: "Erosion and siltation controls: During construction, appropriate erosion and siltation controls must be used and maintained in effective operating condition in accordance with State regulations. All exposed soil and other fill material must be permanently stabilized." On May 27, 2004, this office was notified by the BCCD that appropriate soil erosion and sedimentation controls had not been installed on the site in accordance with State laws and the Best Management Practice requirements of the PASPGP-2. The BCCD identified numerous violations during the period from November 3, 2003 through May 27, 2004.

Work performed in noncompliance with Conditions and/or Special Conditions of a permit is a violation of Section 404 of the Clean Water Act.

As of the date of this letter, you have removed the unauthorized dredged and/or fill material at Crossing #5. However, the hydrologic connection on the eastern side of Crossing #5 has not been reestablished. During a meeting in this office on August 9, 2004, you agreed to perform the corrective measures necessary to restore the hydrologic connection between wetlands on the eastern side of Crossing #5. You are directed to complete all restoration work, including reestablishing the above noted hydrologic connection, within 20 days of the date of this letter.

In order to resolve the above noted Clean Water Act violations voluntarily, K. Hovnanian Companies, Inc. must comply fully with the following conditions:

- 1) K. Hovnanian Companies, Inc. shall contribute \$27,500.00 to a nonprofit conservation organization approved by the Corps of Engineers (Corps). The Corps-approved nonprofit conservation organization shall use the contribution to purchase waters, wetlands, and associated upland buffers and/or to purchase conservation easements over waters, wetlands, and associated upland buffer in Bucks and/or Montgomery Counties, Pennsylvania; and
- 2) K. Hovnanian Companies, Inc. shall confirm the above transaction by obtaining a letter from the Corps approved non-profit conservation organization confirming its receipt of the \$27,500.00 contribution and setting forth its agreement to utilize the money as described in paragraph "1" above. This office shall be provided a copy of the letter from the approved non-profit conservation organization and a copy of the check or proof of wire transfer no later than three days from receipt by the approved non-profit conservation organization.

Following completion of the restoration work, the restored area will be inspected by a representative of this office.

If this office receives the required confirmation from the Corps-approved non-profit conservation organization as specified above, and the hydrologic connection noted above is restored satisfactorily, then:

a) The Corps shall take no further action against K. Hovnanian Companies, Inc. or any of its general partners, contractors or subcontractors with regard to any Clean Water Act, Section 404(s) violations that occurred prior to the date of this letter associated with construction of the subject project; and

b) The Cease and Desist order of July 27, 2004 shall be immediately withdrawn and rescinded. The withdrawal and rescission of the Cease and Desist order shall be verified telephonically and shall be confirmed by letter from this office.

Your agreement to meet the above noted conditions would resolve the Clean Water Act Section 404(s), violations that occurred prior to the date of this letter at the above noted property. This resolution does not eliminate, suspend, or delay the requirement for your compliance with any other conditions, including Special Conditions, of the above noted permit.

Should you have any questions regarding this matter, please contact Michael F. Green at (215) 656-6836.

Sincerely,

Frank J. Cianfrani Chief, Regulatory Branch

Copies Furnished:

US Fish and Wildlife Service, State College, PA
US Environmental Protection Agency, Region III, PA
PA Department of Environmental Protection, Norristown, PA
Northampton Township
Bucks County Soil Conservation District

Trib 02642 To Little Neshaminy Creek


Aquatic Life

Non-Attainment

Urban Runoff/Storm Sewers/Siltation:1998

Urban Runoff/Storm Sewers/Water/Flow Variability:1998

1.



Trib 02642 To Little Neshaminy Creek


Aquatic Life

Non-Attainment


Urban Runoff/Storm Sewers/Siltation:1998

Urban Runoff/Storm Sewers/Water/Flow Variability:1998

1.



Trib 02642 To Little Neshaminy Creek
Aquatic Life
Non-Attainment
Urban Runoff/Storm Sewers/Siltation:1998
Urban Runoff/Storm Sewers/Water/Flow Variability:1998
1.



Trib 02642 To Little Neshaminy Creek
Aquatic Life
Non-Attainment
Urban Runoff/Storm Sewers/Siltation:1998
Urban Runoff/Storm Sewers/Water/Flow Variability:1998

1.

